



Circa 2013

Front and north
façades facing
south



August 2016

Front and north
façades facing
south

August 2016

Sign



C. 1957

Front façade and sign

Photo courtesy of Ralph M. Pearce

*Ken Ying Low Chinese Restaurant - City Landmark HL09-180 – Before and After Restoration
All photos by City of San Jose staff unless otherwise noted*



2013

Ground floor of
front façade



August 2016

Ground floor of
front façade

*Ken Ying Low Chinese Restaurant - City Landmark HL09-180 – Before and After Restoration
All photos by City of San Jose staff unless otherwise noted*

2013

Balcony over N. 6th Street (facing north)



August 2016

Balcony over N. 6th Street (facing north)



*Ken Ying Low Chinese Restaurant - City Landmark HL09-180 – Before and After Restoration
All photos by City of San Jose staff unless otherwise noted*



2013

Front façade facing north



August 2016

Front façade facing north

*Ken Ying Low Chinese Restaurant - City Landmark HL09-180 – Before and After Restoration
All photos by City of San Jose staff unless otherwise noted*

2013

North façade



August 2016

North façade



C. 1946-1948

Earliest photo of
structure on file
with the City.

Photo courtesy of
Ralph M. Pearce



August 2016



*Ken Ying Low Chinese Restaurant - City Landmark HL09-180 – Before and After Restoration
All photos by City of San Jose staff unless otherwise noted*

August 2016



Circa October 2015

View of front and side façades facing south, after partial demolition, before reconstruction and restoration

